




STONEWORKS HOT/COLD CYCLE TEST

Test Condition:

The film can be influenced by changes in temperature, humidity, sunlight, and other factors. The test is to insure that the film does not crack, blush, lose gloss, adhesion or flexibility.

Test Purpose:

The process for the hot/cold cycle test is as follows: The total cycle time is 5-10 cycles. The sample is put at a constant temperature of -20°C for two hours and then at 50°C constant temperature for two hours. The sample is then visually inspected for cracks, blistering, etc.



Test Results:

No cracking, blistering, etc. was observed.